

COMMISSIONER'S MONTHLY REPORT

Commissioner

Date Sept 6 - 1967  
Report for Month of Sept 1967

Source and Point of Measurement	Day of the Month																																
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31		
	Second feet of water																																
I. Boardman Springs #1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)						3.34																											
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. Water)						—																											
#3. Church ditch near to heading						1.15																											
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)						1.2																											
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake						*																											
II. Thomas Spring #5. Above the Olsen house below the tracks						2.23																											
III. Drain #6. Drain Channel near Railroad Shop and Burningham properties						1.5																											
IV. #8. Levie Ditch - Water to Church Farm, etc.						4.47																											
V. #9. Pump Water at Church Welfare Farm						None																											

Submitted by

E. Lewis Allen

For key to location numbers see drawing P-5107

\* We read  $4\frac{3}{8}$ " of water over weir on 13<sup>th</sup> & 5<sup>th</sup> of which is  
wrong - due to back up in ditch - heavily weeded & restricted flow